# 8D Problem Solving Report

| | |
|---|---|
| **Complaint code** | CR-2026-007 |
| **Customer** | P&G |
| **Type** | internal |
| **Severity** | medium |
| **DueDate** | 2026-01-31 |

## D1 – Team

| | |
|---|---|
| Responsible | 2 |

## D2 – Problem description

A termék szennyezett volt

## D3 – Containment actions

Zárolva

## D4 – Root cause analysis

## D5–D6 – Corrective / Preventive actions

| Type | Description | Responsible | Due date | Status |
|---|---|---|---|---|

## D7 – Effectiveness verification

| | |
|---|---|
| All actions verified | NO |

## D8 – Lessons learned / Closure